

From: [Mayer, Richard](#)
To: [Moore, Gary](#); [Delgado, Paige](#)
Cc: [Ehrhart, Richard](#)
Subject: FW: FJ Doyle Salvage site (SWR 80951)
Date: Friday, August 17, 2018 9:15:42 AM
Attachments: [image002.png](#)
[80951 - Request for Investigation.docx](#)
[Enclosure 1.pdf](#)
[Enclosure 2.pdf](#)
[Enclosure 3.pdf](#)

Gary, The follow up to the original TCEQ request.

From: Allan Posnick [mailto:allan.posnick@tceq.texas.gov]
Sent: Thursday, February 09, 2017 2:39 PM
To: Mayer, Richard <mayer.richard@epa.gov>
Subject: FW: FJ Doyle Salvage site (SWR 80951)

Hey Rich, Here's the additional info. I took a quick glance. It doesn't appear soils have been fully delineated. Don't know how deficient that it. Hope it isn't deal killer. Allan

From: Richard Scharlach
Sent: Thursday, February 09, 2017 2:32 PM
To: Allan Posnick <allan.posnick@tceq.texas.gov>
Subject: FW: FJ Doyle Salvage site (SWR 80951)

Allan

Here are some of the reports related to Ellie's site. We had requested the region to conduct an inspection back in November, but not sure if that happened or not.

Thanks

Richard

From: Erin Gorman
Sent: Thursday, November 10, 2016 11:19 AM
To: Eleanor Wehner <Eleanor.Wehner@tceq.texas.gov>
Cc: Sam Barrett <sam.barrett@tceq.texas.gov>; Richard Scharlach <richard.scharlach@tceq.texas.gov>
Subject: FW: FJ Doyle Salvage site (SWR 80951)

Hi Ellie,

We can definitely work this into our schedule. I'll have to look at investigators schedules to see when we could go out; it will most likely be a few months. If you would like to discuss, I'm available

today until 12:45 pm and then again from 3 -4 pm. Or next week. I have a conference on Tuesday and will be traveling on Monday, so Wednesday or after I'll be available.

Erin

From: Eleanor Wehner
Sent: Thursday, November 10, 2016 10:41 AM
To: Erin Gorman <erin.gorman@tceq.texas.gov>
Cc: Richard Scharlach <richard.scharlach@tceq.texas.gov>
Subject: FJ Doyle Salvage site (SWR 80951)

Hi Erin:

It's me again! I have a CA case located in R-4 (SWR 80951; FJ Doyle Salvage located at 905 N. Poplar Street, Leonard (Fannin County) Texas; EPA ID No. TXD980865109; CN600359095; RN100649227). I have been working with the owner for several years to address existing historic contamination issues (impacts to soil identified through EPA sampling investigations conducting in the 1990's) and IHW registration unit closure issues. I would like to discuss the case with someone in R-4 to see if it would be possible to work this site into future R-4 IHW site investigation planning efforts in the next few years. I have prepared an IOM (copy attached) that I am preparing to send to R-4 to formally request assistance/initiate discussions concerning the case.

I am trying to build sufficient case documentation to issue a NOV/refer the case to Enforcement (for waste-related violations) to address closure of WMUs and initiate assessment/cleanup of PCB, metals and petroleum hydrocarbon contamination issues that are documented onsite as well as on offsite residential property. The property sits adjacent to a high school and day care, public water supply well within 500 feet of the property.

I have attached a copy of IOM requesting assistance including supporting documents...hoping there is some way to get the site on the R-4 radar for IHW site investigation in the next few years to at least verify/document current physical conditions of the site, WMUs, etc.?

Eleanor Wehner, PG | TCEQ Remediation Division, VCP-CA Section
12100 Park 35 Circle, Bldg. D | Austin, Texas 78753 | Mail: MC-127, P.O. Box 13087, Austin TX 78711-3087
(512) 239-6542 | Fax: (512) 239-2346 | Eleanor.Wehner@tceq.texas.gov

